## Renergy Land Application Operator Daily Log \*NOTE: All information required to be completed

Site #: Mos - 05 - 05-		quired to be comple Date	:7/29/17	
Hours of Operation:	_am/pm	to	6 pm.	am/pm
Weather Conditions: Survey	<u>_80°</u>			
Are signs posted? (Yes)	No	Buffers Flagged?	Yes	No
Does the field have drainage tiles?	Yes	No		
Are tile outlets plugged? Yes	No			
Inspected for suitable risers, hoses, and connectors at:	Start up	In process	End day/field	
Method of application? Surface appli	ication	Injection		
lext year's crop:		_		
pplication rate per acre: 10,000		_		
lumber of loads to site: 43	·	_		
allons applied to this site on this date:	2560	77	_	
approximate acres applied on this date:	25		<del>-</del>	
Notes:				
Operator Name: Naw Manishus	LLO.			
Operator Signature:				
energy Employee Signature:	- Care Cr	,		
Call Taylor Faecher (513) 476-1663, Envi			-	

ENV-017 Rev. 12/7/16

Call Logan Randles (614) 961-6713, Director of Operations

## **Renergy Land Application Operator Daily Log**

\*NOTE: All information required to be completed Site #: 105-03-08 Hours of Operation: am/pm Weather Conditions: Summy Are signs posted? No **Buffers Flagged?** Yes No Does the field have drainage tiles? Yes Are tile outlets plugged? Yes No Inspected for suitable risers, hoses, Start up In process End day/field and connectors at: Method of application? Surface application Injection Next year's crop: Application rate per acre: 10 500 Number of loads to site: 42Approximate acres applied on this date: 27Notes: **Operator Name** Operator Signature: Renergy Employee Signature:

Call Taylor Faecher (513) 476-1663, Environmental Compliance Specialist Call Logan Randles (614) 961-6713, Director of Operations

ENV-017 Rev. 12/7/16

## **Renergy Land Application Operator Daily Log** \*NOTE: All information required to be completed Site #: MOS -O3 - S Date: 8 Hours of Operation: Sam am/pm Weather Conditions: SUNNY Are signs posted? **Buffers Flagged?** No Yes No Does the field have drainage tiles? Yes No Are tile outlets plugged? Yes No Inspected for suitable risers, hoses, End day/field Start up / In process and connectors at: Method of application? Surface application Injection Next year's crop: Application rate per acre: 10,000 gallor

Gallons applied to this site on this date: <u>23フ ラクム</u>

Number of loads to site: 39.

Approximate acres applied on this date:

Notes:

Operator Name:

Jers MANDUNG LLE

Operator Signature:

Renergy Employee Signature:

Call Taylor Faecher (513) 476-1663, Environmental Compliance Specialist Call Logan Randles (614) 961-6713, Director of Operations

ENV-017 Rev. 12/7/16

## Renergy Land Application Operator Daily Log \*NOTE: All information required to be completed

Site #: <u>MOS - 03 - 08</u>	Date: 8/2/17			
Hours of Operation: <u>Jan</u>	(am)/pm	to	12:30	am/pm)
Weather Conditions: Source	n 75	0		
Are signs posted? Yes	No	Buffers Flagged?	(Yes)	No
Does the field have drainage tiles?	Yes	No	The second secon	
Are tile outlets plugged? Yes	No			
Inspected for suitable risers, hoses, and connectors at:	Start up	In process	End day/field	
Method of application? Surface app	lication (	Injection		
Next year's crop:				
Application rate per acre: 10 000	gulla.	_		
Number of loads to site:		<u>-</u>		
Gallons applied to this site on this date	•		_	
Approximate acres applied on this date	: 87,2	<u> </u>	-	
Notes:				
Operator Name:	om trapate - 1	<i>r</i> , o		
Operator Signature:	DUWIS L	have floreness.		
Renergy Employee Signature:	- Face	<u> </u>		
Call Taylor Faecher (513) 476-1663, Env Call Logan Randles (614) 961-6713, Dire		-	t	

ENV-017 Rev. 12/7/16

MOS-03-08 Setback Distance